



GARY R. HERBERT  
Governor

SPENCER J. COX  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER  
Executive Director

### Division of Oil, Gas and Mining

JOHN R. BAZA  
Division Director

July 29, 2016

Certified Return Receipt Requested  
7013 2250 0000 2310 2552

Brent Sumsion  
Sunroc Corporation  
P. O. Box 1955  
Orem, Utah 84059

Subject: Division Directive to Repair Road Damage and Remove Undercut Highwall, Sunroc Corporation, Levan Henry Mine, M/023/0023, Juab, County, Utah

Dear Mr. Sumsion:

A representative of the Division of Oil, Gas and Mining inspected the Levan Henry mine on July 13, 2016. The inspector noted two items that need to be addressed: an undercut highwall and erosion on the main access road.

Rule R647-4-107.1 requires the operator to minimize hazards to the public safety and welfare. The undercut highwall is unstable and should be removed or otherwise remediated to prevent a slope failure.

Rule R647-4-107.3 requires that the Operator adequately control sediment from the disturbed area. The Notice of Intention to Commence Large Mining Operations (Notice) says on page IV-2:

Access roads into the mines will be graded so that water will flow back into the hillside. The road will have a borrow ditch along the hillside. The downhill side of the road will have a berm to prevent trucks from going over the hill and to retain water.

By September 1, 2016, you are hereby directed to:

- Eliminate the undercut highwall.
- Comply with the commitments on page IV-2 of the Notice regarding road maintenance. At a minimum:
  - Grade the access road so water will flow back into the hillside.
  - Construct/repair the borrow ditch along the hillside.
  - Repair the berm on the downhill side to retain water.






Page 2 of 2  
Sunroc Corporation  
M/023/0023  
July 29, 2016

Please contact Wayne Western at 801-538-5263 or me at 801-538-5261 if you have questions or concerns regarding this letter. Thank you for your help in completing these regulatory requirements.

Sincerely,

A handwritten signature in black ink, appearing to read "P. Baker", written over a horizontal line.

Paul B. Baker  
Minerals Program Manager

PBB: whw: eb  
Enclosure: Inspection Report

cc: Tom Lloyd, Forest Service (twlloyd@fs.fed.us)  
Steven Polgar, MSHA (Polgar.Steven@dol.gov)

P:\GROUPS\MINERALS\WP\M023-Juab\M0230023-Henry1and2\final\Directive-7474-07192016.docx